

Model:T2118 1

Catalogue

Brief 3
Frame Installation 4
Force Arm Installation 5
Leg Press Frame Installation 6
Cushion Installation 7
Cable Installation 8
Cover Installation 9
Accessories List 10

Model:T2118 2

Brief

Please take the time to carefully read the instruction before installing. Please refer to the manual to determine the list of all components were packaged well. Cliff there have some parts missed or damaged please immediately call our customer service department. Please refer to the installation instruction while installing.

This device designed to provide the most effective and smoothest training movements. After installing, you can only know how to use the products after you have all the functions. If there is any question, please check the installation instruction and find out the wrong steps during the installing. If still not work, please contact the distributors authorized by original factory. The code and manual will be needed.

Tools

Rubber stick
Levelling instrument
Civilly pliers
Socket head screw wrench
The adjustable wrench
More than 2 person

Model:T2118 3

Installation of Frame

CAUTION:
The wrench need to tighten the hardware

Important Notification:
All T2 Products with balance weight, please put the lower cover in the balance weight frame before installing the connecting rack .

Model:T2118 4

Force Arm Installation

CAUTION:
The wrench need to tighten the hardware
Some assembly have been omitted for clarity



Model:T2118 5

Leg Press Frame & Foot Pad Installation

CAUTION:
The wrench need to tighten the hardware

Model:T2118 6

Cushion Installation

CAUTION:
The wrench need to tighten the hardware
Some assembly have been omitted for clarity

Model:T2118 7

Cable Installation

Fine tuning:
Loosen the safety nut and whole plate
Refit to the proper tension on cable

Important Notification:
Please read the T2000-Illustration Instruction as the reference to install the balance weight frame and required accessories

Model:T2118 8

Cover Installation

Important Notification:
Now T218 has been assembled. You need to take the time to make sure your machine is adjusted correctly. The cable should be in the center of the pulley and pulley should be perpendicular to the bar directions. If not, then you have to loosen some of the vertical frame reasonably hardware and tighten the bolts.

Model:T2118 9

Accessories List

Caution:Some spare parts which have been assembled are not in the list

NO.	Name & Specification	Material	Qty
1	Balance Weight Frame	Element	1
2	Body Frame	Element	1
3	Hexagon socket button head screws(M10*45)	45	2
4	Force arm	Element	1
5	Directing arm	Element	2
6	Inner Hexagon countersunk head screws(M8*45)	45	3
7	D=90mm pedals	PA	2
8	D92handles cover	Thermoplastic	2
9	Bearing	Bearing steel	2
10	Hexagon socket head cap screws(M12*25)	45	2
11	Flange plate	Element	1
12	Deep Groove Ball Bearing(6208	Bearing steel	2
13	Bearing sleeve	45	1
14	Deep Groove Ball Bearing(6207	Bearing steel	2
15	Deep Groove Ball Bearing(6205	Bearing steel	2
16	Bearing sleeve	45	1
17	Hexagon socket button head screws(M12*25)	45	2
18	1000ball cover	Thermoplastic	2
19	Leg press frame	Element	1
20	D2holding	PA	2
21	Allen+shifter shaft(4.8*45)	45	1
22	Hexagon socket button head screws(M10*25)	45	2
23	Lubrication pad	Rubber	2
24	Foot pad(Short one)	Rubber	2
25	Cushion	Element	1
26	Hexagon socket button head screws(M8*25)	45	2
27	Cushion	Element	1
28	Back pad	Element	1
29	Hexagon socket head cap screws(M10*60)	45	4
30	Wire rope	Element	1

Model:T2118 10